

Item P11-7160

3-Phase/Motor Rotation Tester

Identifies three-phase sequences and indicates motor rotation. Checks for open phases. For use up to 600V.

Item	Description	Attributes
11-7160	3-Phase/Motor Rotation Tester	