



**Item P12-0872**

**Polyester Measure/Pulling Tape**

A Measuring and Pulling tape in one! Reduces the amount of time it takes to measure and pull in your cable versus using a separate measuring tape and pulling tape. Blow one line into a duct, measure the length of the run and then pull in your cable. Durable and stretch resistant for easily pulling and installing wire and fiber optic cables within PVC and HDPE ducts. Factory lubricated to reduce friction and burn-through in innerduct. Easy to read foot marking for quick and accurate measurements.

Item	Description	Attributes
12-0872		<b>Avg. Breaking Strength:</b> 1,250 lbs. <b>Length:</b> 3000' <b>Width:</b> 1/2"
12-0873		<b>Avg. Breaking Strength:</b> 1,800 lbs. <b>Length:</b> 3000' <b>Width:</b> 5/8"
12-0874		<b>Avg. Breaking Strength:</b> 2,500 lbs. <b>Length:</b> 3000' <b>Width:</b> 3/4"