



**Item P50-1257**

**RDX Series Standard Replacement Charging Tray**

Charging tray usually takes 10 hours to fully charge RDX Series two-way radios.

Item	Description	Attributes
50-1257	RDX Series Standard Replacement Charging Tray	